

SERVICE PROVIDER CERTIFICATE

REFERENCE: EASA.AOA.DAT.028

Pursuant to Implementing Regulation (EU) 2017/373 and subject to the conditions specified below, the European Union Aviation Safety Agency hereby certifies

CMC Electronics Inc.

600 Dr. Frederik Philips Boulevard
Ville Saint-Laurent, Quebec
H4M 2S9
CANADA

as a service provider with the privileges, as listed in the attached service provision conditions.

CONDITIONS:


This certificate is issued subject to the conditions and the scope of providing services and functions as listed in the attached service provision conditions.

This certificate is valid whilst the certified service provider remains in compliance with Implementing Regulation (EU) 2017/373 and the other applicable regulations and, when relevant, with the procedures in the service provider's documentation.

Subject to compliance with the foregoing conditions, this certificate shall remain valid unless the certificate has been surrendered, limited, suspended or revoked.

Date of issue: 12th December 2025

For the European Union Aviation Safety Agency,



Manuel RIVAS VILA
ATM Oversight Section Manager

SERVICE PROVIDER CERTIFICATE

Service Provision Conditions

Attachment to service provider's certificate:

Reference: EASA.AOA.DAT.028

CMC Electronics Inc.

has obtained the privileges to provide the following scope of services/functions:

Services/Functions	Type of Service/Function	Scope of Service/Function	Limitations
Data Services (DAT)	Type 2	Provision of Type 2 DAT authorises the supply of aeronautical databases to end-users/aircraft operators for the following airborne application/equipment, for which compatibility has been demonstrated: Flight management system (FMS) Equipment Model: CMA-900 Part No Hardware: 100-601900-202 Software: 169-612830-600, 169-612830-601, 169-612830-602, 169-612830-603, 169-612830-604, 169-612830-606 P/N Hardware: 100-601900-402 Software: 169-614147-003, 169-614147-004, 169-614147-005E, 169-614147-006, 169-614147-007, 169-614147-008, 169-614147-009, 169-614147-010, 169-614147-100, 169-614147-101, 169-614147-102, 169-614147-103, 169-614147-110, 169-614147-111, 169-614147-112, 169-614147-120, 169-614147-140 Flight Management System (FMS) Equipment model: CMA-3000 Part No Hardware: 100-601721-000 to -003 Software: 169-614000-002 Part No Hardware: 100-601721-000 to -003 Software: 169-614000-005 to -009 (Except 169-614000-006)	

		Part No Hardware: 100-601721-003 Software: 169-614000-004 Flight Management System (FMS) Equipment Model: CMA-9000 P/N Hardware: 100-601951-001, 002, 003, 005 Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-614876-300 W, 169-614876-310 J P/N Hardware: 100-601951-030 Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-616414-057, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-430 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-616414-057, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-045, 060 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-616414-056, 169-616414-057, 169-616414-057 A, 169-616414-058, 169-616414-059, 169-616414-060, 169-616414-061, 169-616414-061 A, 169-616414-061 B, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-	
--	--	--	--

		616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-050 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-070 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-614876-300 W, 169-614876-310 J P/N Hardware: 100-601951-101, 102, 103 Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-616414-057, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-106 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-290 Software: 169-614876-300, 169-614876-300 W, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-340,
--	--	---

		169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-301 Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-614876-300 W, 169-614876-310 J P/N Hardware: 100-601951-302 Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-614876-300 W P/N Hardware: 100-601951-303 Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-616414-057, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-445 Software: 169-614876-040, 169-614876-050G, 169-614876-055, 169-614876-056, 169-616414-056, 169-616414-057, 169-616414-057 A, 169-616414-058, 169-616414-059, 169-616414-060, 169-616414-061, 169-616414-061 A, 169-616414-061 B, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-450 Software: 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A,	
--	--	--	--

	169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-451 Software: 169-616414-061, 169-616414-061 A, 169-616414-061 B P/N Hardware: 100-601951-452 Software: 169-616414-061 A, 169-616414-061 B P/N Hardware: 100-601951-460, 470 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-616414-056, 169-616414-057, 169-616414-057 A, 169-616414-058, 169-616414-059, 169-616414-060, 169-616414-061, 169-616414-061 A, 169-616414-061 B, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-471 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-472 Software: 169-614876-640, 169-614876-655, 169-614876-655A P/N Hardware: 100-601951-480 Software: 169-614876-700 G P/N Hardware: 100-601951-501, 502, 503 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-616414-057, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-
--	---

		616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-506 Software: 169-614876-040, 169-614876-050 G, 169-614876-055, 169-614876-056, 169-614876-300 W, 169-614876-310 J, 169-616414-310 J, 169-616414-310 K, 169-616414-312, 169-614876-313, 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-541 Software: 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 A, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-542, 543, 545 Software: 169-614876-320, 169-616414-320, 169-616414-320 A, 169-616414-320 B, 169-616414-321, 169-616414-322, 169-616414-322 A, 169-616414-323, 169-616414-323 B, 169-616414-330, 169-616414-331, 169-616414-331 A, 169-616414-340, 169-616414-340 A, 169-616414-340 B, 169-616414-341, 169-616414-342 P/N Hardware: 100-601951-745 Software: 169-616414-061, 169-616414-061 A, 169-616414-061 B P/N Hardware: 100-601951-760 Software: 169-616414-061, 169-616414-061 A, 169-616414-061 B P/N Hardware: 100-601951-770 Software: 169-616414-061, 169-616414-061 A, 169-616414-061 B Flight Management System (FMS) Equipment model: CMA-9000M P/N Hardware: 100-601951-480	
--	--	---	--

		Software: 169-614876-700 GLSSU Equipment model: CMA-5024 P/N Hardware: 100-601967-100, 105 Software: 169-615116-001, 169-615116-020, 169-615116-020E, 169-615116-020F P/N Hardware: 100-601967-101 Software: 169-615116-030, 169-615116-030D P/N Hardware: 100-601967-102 Software: 169-615116-030D P/N Hardware: 100-601967-103, 106, 107, 108 Software: 169-615116-030, 169-615116-030D P/N Hardware: 100-601967-110 Software: 169-615116-020, 169-615116-020E, 169-615116-020F P/N Hardware: 100-601967-111 Software: 169-615116-030, 169-615116-030D, 169-615116-630 P/N Hardware: 100-601967-112, 113 Software: 169-615116-020E, 169-615116-020F P/N Hardware: 100-601967-114, 115 Software: 169-615116-035 P/N Hardware: 100-601967-121 Software: 169-615116-031 P/N Hardware: 100-601967-122 Software: 169-615116-030D P/N Hardware: 100-601967-200 Software: 169-615116-020, 169-615116-020E, 169-615116-520 P/N Hardware: 100-601967-202, 203, 208, 403 Software: 169-615116-030, 169-615116-530 P/N Hardware: 100-601967-301, 303 Software: 169-615116-030, 169-615116-030D P/N Hardware: 100-601967-302, 304 Software: 169-615116-030D P/N Hardware: 100-601967-116, 117, 130, 150 Software: 169-616881-001 P/N Hardware: 100-601967-210	
--	--	--	--

		Software: 169-616881-501 GPS/SBAS landing system sensor unit (GLSSU) Equipment model: CMA-5024 Part No Hardware: 100-604095-1XX, -3XX Software: 169-616881-001, 169-616881-002 Part No Hardware: 100-604095-2XX, 4XX Software: 169-616881-501, 169-616881-502 GBAS GLSSU Equipment model: CMA-6024 P/N Hardware: 100-604076-100, 100-604076-103 Software: 169-616881-001 P/N Hardware: 100-604076-102 Software: 169-616881-001, 169-616881-002 P/N Hardware: 100-604076-201 Software: 169-616881-501 P/N Hardware: 100-604076-202 Software: 169-616881-501, 169-616881-502 Part No Hardware: 100-604095-3XX Software: 169-616881-001, 169-616881-002 Part No Hardware: 100-604095-4XX Software: 169-616881-501, 169-616881-502 Integrated Avionics System (IAS) Equipment model: C4X IAS P/N Hardware: 100-602580-000, 001, 002: Software: 169-615186-001, 169-615186-002, 169-615186-003 P/N Hardware: 100-602580-102 Software: 169-615186-003 P/N Hardware: 100-602580-103 Software: 169-615186-004 P/N Hardware: 100-602580-104 Software: 169-615186-005 P/N Hardware: 100-602580-105 Software: 169-615186-006	
Conditions			

Date of issue: 12th December 2025

For the European Union Aviation Safety Agency,



Manuel RIVAS VILA
ATM Oversight Section Manager