

## SERVICE PROVIDER CERTIFICATE

**REFERENCE: EASA.AOA.DAT.028**

Pursuant to Implementing Regulation (EU) 2017/373 and subject to the conditions specified below, the European Union Aviation Safety Agency hereby certifies

### **CMC Electronics Inc.**

600 Dr. Frederik Philips Boulevard  
Ville Saint-Laurent, Quebec  
H4M 2S9  
CANADA

as a service provider with the privileges, as listed in the attached service provision conditions.

#### CONDITIONS:

This certificate is issued subject to the conditions and the scope of providing services and functions as listed in the attached service provision conditions.

This certificate is valid whilst the certified service provider remains in compliance with Implementing Regulation (EU) 2017/373 and the other applicable regulations and, when relevant, with the procedures in the service provider's documentation.

Subject to compliance with the foregoing conditions, this certificate shall remain valid unless the certificate has been surrendered, limited, suspended or revoked.

**Date of issue: 18<sup>th</sup> September 2024**

**For the European Union Aviation Safety Agency,**



**Manuel RIVAS VILA**  
**ATM Oversight Section Manager**

# SERVICE PROVIDER CERTIFICATE

## Service Provision Conditions

Attachment to service provider's certificate:

Reference: EASA.AOA.DAT.028

CMC Electronics Inc.

has obtained the privileges to provide the following scope of services/functions:

Services/Functions	Type of Service/Function	Scope of Service/Function	Limitations
Data Services (DAT)	Type 2	Provision of Type 2 DAT authorises the supply of aeronautical databases to end-users/aircraft operators for the following airborne application/equipment, for which compatibility has been demonstrated:  Flight management system (FMS)  Equipment model: CMA-900  Part No Hardware: 100-601900-202/ Software: 169-612830-600 to -604  Part No Hardware: 100-601900-202/ Software: 169-612830-606  Part No Hardware: 100-601900-402/ Software: 169-614147-003  Part No Hardware: 100-601900-402/ Software: 169-614147-004  Part No Hardware: 100-601900-402/ Software: 169-614147-005E  Part No Hardware: 100-601900-402/ Software: 169-614147-006 to -010  Part No Hardware: 100-601900-402/ Software: 169-614147-100 to -103  Part No Hardware: 100-601900-402/ Software: 169-614147-110 to -112  Part No Hardware: 100-601900-402/ Software: 169-614147-120  Part No Hardware: 100-601900-402/ Software: 169-614147-140	





	<p>Equipment model: CMA-3000</p> <p>Part No Hardware: 100-601721-000 to -003/ Software: 169-614000-002</p> <p>Part No Hardware: 100-601721-000 to -003/ Software: 169-614000-004 to -009 (Except 169-614000-006)</p> <p>Equipment model: CMA-9000</p> <p>Part No Hardware: 100-601951-001 to -003/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-005/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-030/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-045/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-050/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055,</p>	
--	--	--



	<p>169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-060/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-070/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-101 to -103/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-106/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-290/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300,</p>	
--	---	--



	<p>169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-301 to -302/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-303/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-430/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-445/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware 100-601951-450: Software 169-614876-320, 169-616414-320, 169-616414-321, 169-</p>	
--	--	--



	<p>616414-322, 169-616414-323, 169-616414-330, 169-616414-331, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware 100-601951-451 to 452: Software 169-616414-061.</p> <p>Part No Hardware: 100-601951-460/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-470 to -471/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-472/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-501 to -503/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057, 169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware: 100-601951-506/ Software: 169-614876-001, 169-614876-010, 169-614876-020, 169-614876-022, 169-614876-040, 169-614876-300, 169-614876-640, 169-614876-050, 169-614876-055, 169-614876-056, 169-614876-310, 169-614876-313, 169-614876-320, 169-614876-655, 169-616414-057,</p>	
--	---	--

	<p>169-616414-056, 169-616414-060, 169-616414-310, 169-616414-312, 169-616414-320 to -323, 169-616414-330, 169-616414-331, 169-616414-061, 169-616414-058, 169-616414-059, 169-616414-340, 169-616414-341.</p> <p>Part No Hardware 100-601951-541, 542, 543 and 545: Software 169-614876-320, 169-616414-320, 169-616414-321, 169-616414-322, 169-616414-323, 169-616414-330, 169-616414-331, 169-616414-340, 169-616414-341</p> <p>Part No Hardware: 100-601951-745, -760, -770/ Software: 169-616414-061</p> <p>Equipment model: CMA-9000M</p> <p>Part No Hardware: 100-601951-480/ Software: 169-614876-700</p> <p>GPS/SBAS landing system sensor unit (GLSSU)</p> <p>Equipment model: CMA-5024</p> <p>Part No Hardware: 100-601967-1xx/ Software: 169-615116-001, 169-615116-020</p> <p>Part No Hardware: 100-601967-2xx/ Software: 169-615116-001, 169-615116-020</p> <p>Part No Hardware: 100-601967-1xx (Except 100-601967-100, 100-601967-105 and 100-601967-110)/ Software: 169-615116-030, 169-615116-035, 169-615116-630, 169-615116-031, 169-616881-001</p> <p>Part No Hardware: 100-601967-2xx (Except 100-601967-200)/ Software: 169-615116-520, 169-615116-530, 169-616881-501</p> <p>Part No Hardware: 100-601967-3xx/ Software: 169-615116-030, 169-615116-035, 169-615116-630, 169-615116-031, 169-616881-001</p> <p>Part No Hardware: 100-601967-4xx/ Software: 169-615116-520, 169-615116-530, 169-616881-501</p> <p>Part No Hardware: 100-604095-1xx/ Software: 169-616881-001, 169-616881-002</p> <p>Part No Hardware: 100-604095-3xx/ Software: 169-616881-001, 169-616881-002</p> <p>Part No Hardware: 100-604095-2xx/ Software: 169-616881-501, 169-616881-502</p> <p>Part No Hardware: 100-604095-4xx/ Software: 169-616881-501, 169-616881-502</p> <p>Equipment model: CMA-6024</p> <p>Part No Hardware: 100-604076-1xx/ Software: 169-616881-001, 169-616881-002</p>	
--	--	--



	<p>Part No Hardware: 100-604076-2xx/ Software: 169-616881-501, 169-616881-502</p> <p>Part No Hardware: 100-604076-3xx/ Software: 169-616881-001, 169-616881-002</p> <p>Part No Hardware: 100-604076-4xx/ Software: 169-616881-501, 169-616881-502</p> <p>Integrated Avionics System (IAS) Equipment model: C4X IAS</p> <p>Part No Hardware: 100-602580-000/ Software: 169-615186-001, 169-615186-002, 169-615186-003</p> <p>Part No Hardware: 100-602580-001/ Software: 169-615186-001, 169-615186-002, 169-615186-003</p> <p>Part No Hardware: 100-602580-002/ Software: 169-615186-001, 169-615186-002, 169-615186-003</p> <p>Part No Hardware: 100-602580-102/ Software: 169-615186-003</p> <p>Part No Hardware: 100-602580-103/ Software: 169-615186-004</p> <p>Part No Hardware: 100-602580-104/ Software: 169-615186-005</p> <p>Part No Hardware: 100-602580-105/ Software: 169-615186-006</p>	
Conditions		

Date of issue: 18<sup>th</sup> September 2024

For the European Union Aviation Safety Agency,



**Manuel RIVAS VILA**  
ATM Oversight Section Manager